

# twilight

INSTRUMENTOS DE MEDICIÓN INDUSTRIAL

## **Analizador de humedad Fuzhou FZ-MA100C**

[www.twilight.mx](http://www.twilight.mx)



/ twilightsadecv




/ twilightsadecv



/ twilightsadecv

# Moisture Analyzer Operation Manual



## Table of Contents

|  |    |
|--|----|
| 1. Overview.....                         | 2  |
| 1.1 Overview.....                        | 2  |
| 1.2 Safety precaution.....               | 3  |
| 2. Installation.....                     | 5  |
| 3. Operating.....                        | 6  |
| 3.2 Display's Signal.....                | 6  |
| 3.3 Keypad.....                          | 7  |
| 4. Parameter settings.....               | 8  |
| 4.1 Parameter settings.....              | 9  |
| 4.2 Temperature setting.....             | 10 |
| 4.3 Testing mode setting.....            | 10 |
| 4.4 Heating mode setting.....            | 11 |
| 4.5 Timing mode setting.....             | 11 |
| 4.6 User-defined.....                    | 12 |
| 5. Calibration.....                      | 12 |
| 6. Testing steps.....                    | 13 |
| 7. Optimize analyzing.....               | 14 |
| 7.1 Heating temperature.....             | 14 |
| 7.2 Heating time.....                    | 14 |
| 7.3 Sample weight.....                   | 15 |
| 7.4 Sample preparation.....              | 15 |
| 7.5 Sample species.....                  | 15 |
| 8. Time setting.....                     | 16 |
| 9. Data communication.....               | 16 |
| 9.1 RS232 data setting .....             | 17 |
| 9.2 RS232 pin .....                      | 17 |
| 10. Data Storage.....                    | 18 |
| 11. Maintenance and troubleshooting..... | 18 |
| 12. Warranty.....                        | 19 |

### 1.1 About moisture analyzer

Moisture analyzer is a water measurement instrument equipped with high-precision sensors and high-efficiency secondary thermal radiation device on the basis of electronic balance to achieve rapid and accurate moisture determination. Moisture analyzer

The Moisture analyzer is based on the thermodynamic principle, which obtains the moisture percentage content and other results by the ratio of mass to wet weight after material drying.

Moisture analyzers can pre-store a variety of different sample moisture determination methods, making testing work fast and simple. Multiply productivity and accuracy of measurement results compared to mechanical products. The average sample can be measured in just a few minutes. The instrument is simple to operate, accurate to test, the display part of the value is clearly visible, and can display the moisture content value, dry matter content value, sample initial value, final value, measurement time, temperature and other data. And has the function of connecting with the computer and printer.

The Moisture analyzer can be widely used in all industries that need to quickly analyze the moisture, to reach the requirements of various industries, such as plastics, rubber, chemicals, medicine, food, and other industries in the production and experimental process.

## 1.2 Safety precaution

In order to use the moisture analyzer safely and reliably, be sure to comply with the following terms:

1.2.1. This instrument is use for measuring the moisture content of the samples. Any improper operation may cause personal injury and damage to the instrument.

1.2.2. Please confirm that the input voltage and plug type indicated on the label match the AC power used in your area.

1.2.3 The power plug of this instrument is equipped with a grounding terminal. It is forbidden to disconnect the grounding plug of the instrument. Do not switch the size and frequency of the input supply voltage during the test.

1.2.4 Do not operate the moisture analyzer in a dangerous, humid or unstable environment.

1.2.5 Unplug the power supply when cleaning the moisture analyzer.

1.2.6 Make sure there is enough space around the moisture analyzer and at least 1 meter above it.

1.2.7 The moisture analyzer must be operated only by trained personnel who are familiar with the performance of the tested sample and the operation of the equipment.

Please use the relevant safety things to operate the moisture analyzer, such as safety glasses, gloves, protective clothing and protective masks.

1.2.8 After-sales service should only be provided by authorized personnel from the factory.

### **The moisture analyzer works by heating!**

- ★ Do not place any flammable materials above, below or next to the moisture analyzer.
- ★ When using the moisture analyzer, the samples, heating halogen lamps and surrounding components can be very hot. Extra care should be taken when moving samples to prevent burns.
- ★ **Some samples require special care**
- ★ Carefully analyze the possible dangerous consequences for any sample material with safety hazards.

- ★ Fire/Explosion: Flammable and explosive sample heating with solvents produces flammable and explosive gases or vapors, so they need to be carried out in dry, low-temperature environments to prevent fire or explosion.
- ★ Toxic/combustible: Samples of toxic or corrosive components should be carried out in a well-ventilated environment, and such samples will release toxic and corrosive gases during heating, so it is recommended to use as few samples as possible.
- ★ **Note: The user is should take all responsibilities for any damage caused by testing the above types of samples.**

#### **Specification of moisture analyzer**

|                               |                          |        |       |
|-------------------------------|--------------------------|--------|-------|
| Max weighing                  | 100g                     | 100g   | 100g  |
| Display division              | 0.001g                   | 0.005g | 0.01g |
| Readability<br>(sample > 10g) | 0.01%                    | 0.05%  | 0.1%  |
| Heating source                | Halogen lamp             |        |       |
| Temperature setting           | 45°C - 160°C             |        |       |
| Weight calibration            | 100g                     |        |       |
| Pan Size                      | φ110 (mm)                |        |       |
| Dimensions                    | (D*W*H) 330*205*165(mm)  |        |       |
| Package                       | (D*W*H) 410*315*335 (mm) |        |       |
| Net weight                    | 3.2kg                    |        |       |
| Gross weight                  | 4.6kg                    |        |       |

## 2. Installation




2.1 Unpack carefully and check the machine and accessories against the below packing list.

| Standard configuration | Quantity | Remarks                 |
|------------------------|----------|-------------------------|
| Moisture analyzer      | 1        |                         |
| Windshield             | 1        |                         |
| Sample tray holder     | 1        |                         |
| Power cable            | 1        |                         |
| Sample tray            | 1 box    | 5 aluminum pans per box |
| 100g weight            | 1        | F2 Level                |
| operation manual       | 1        |                         |

### 2.2 Placement selection

- ★ The moisture analyzer should be placed on a stable, level surface console.
- ★ Choose a safe and well ventilated location. Samples with corrosive or toxic fumes and other hazardous materials need to be specially prepared for placement.
- ★ Please try to avoid placing the moisture analyzer in places with extreme temperature fluctuations, excessive humidity, airflow, vibration, electromagnetic fields, heat sources or direct sunlight.

### 2.3 Component installation

|   |   |   |
|---|---|---|
|  |  |  |
| ( 1 ) Place the windshield.   | ( 2 ) Place the sample tray holder.   | ( 3 ) Place the sample tray flat on the sample tray holder.                         |


## 2.4 Connect the power supply

Plug the correct end of the supplied power cord into the power input slot on the back of the moisture analyzer, and connect the other end to the power outlet.

**Note: For best measurement results, use or calibrate after at least 60 minutes of power up.**

## 2.5 Adjustment level

The moisture analyzer has a horizontal bubble and two horizontal adjustment feet. To compensate for the effect of the tilting symmetry of the placement position during the weighing process, the horizontal foot can be adjusted until the horizontal bubble is at the center position.




**Note:** The level must be re-adjusted each time the position changes.




## Operation

### 3. Operating


The machine's display





3.1 Display signal description:




|                |      |                                 |                              |   |                      |
|----------------|------|---------------------------------|------------------------------|---|----------------------|
| g              |      | Weigh:grams                     | Automatic mode test accuracy | Hi  | High precision       |
| %              |      | Moisture content%               |                              | M   | Medium precision     |
| ●g             |      | weightlessness                  |                              | Lo  | Low accuracy         |
| 100℃           |      | Temperature (degrees Celsius)   |                              | Hand  | Manual customization |
| 10:00          |      | Time setting (minutes: seconds) | heating method               |  | fast                 |
| Operating mode | Auto | Auto                            |                              |  | standard             |
|                | Time | Time                            |                              |  | slow                 |

3.2 Control panel / keypad



Control panel function description

| Button  | Function key | operating | Features   |
|---|--------------|-----------|--|
|  | Setting      | Hold      | Set heating parameters   |
|   |              | Press     | End of test: switch water content, solid content and other parameters                                      |
|  | Print        | Hold      | Date time setting  |
|   |              | Press     | Print function key after the test is completed; Parameter indicator icon change or numeric increase button |

|   |                |       |   |
|---|----------------|-------|---|
|   | Tare           | Hold  | Tare function key in weighing state;<br>Parameter indicator icon change or number<br>reduction button |
|   |                | Press | Enter calibration function  |
|  | start/st<br>op | Press | Return function after testing   |
|   |                |       | Test start/stop   |
|  | On/off         | Press | On/off  |

## Parameter settings

### 4. Parameter settings

★Select the appropriate working mode

1. Analyze the moisture automatically **Auto**

When machine under auto mode, it will stop the analyzing automatically if sample's moisture changing within very small value.

2. Analyze the sample's moisture manually **Hand**


Use operating keypad manually to measure the sample's moisture according to its character


3. Timed analysis **Time**


User set the analyze time, when time out, the machine will stop the analyzing automatically.

4. High Precision **Hi**、Medium Precision **M**、Low Precision **Lo**

5. The moisture analyzer heating method

Fast heating  Heat to a set temperature in short time

Standard heating  Heat to a set temperature in normal time

Slow heating  Heat to a set temperature in long time

6. Make sure to display the zero value before each test;
7. The sample to be tested is evenly distributed on the surface of the sample tray, and the upper cover of the heating unit is placed down to check whether the sample weight is stable. After the indication is stable, press the “Start/Stop” button to test;
8. When the time is not used or the humidity is large, the relative deviation of the test is large, and the heat engine can be properly used, and the data is not used as a reference. When the substance having a low moisture content is repeatedly tested, it is preferred that the temperature is lowered to normal temperature or 40 degrees or less.

#### 4.1 Parameter settings

The machine can save 16 groups of measuring method and parameters.

User can store 15 groups (from 1-15) of different measuring method and parameters base on different samples, for easy to use.

**Group 16 is the warm up parameter. User can set the machine warm up way base on working mode , time, and temperature.**

Machine warm up can without weighing or samples.

Warm up machine before use can let machine has best working status, can evaporate the water which attached on the pan or tray, to have best measure results. When machine on standby status, short press [SET] and [START] quickly will let machine start to warm up automatically.

#### Parameter settings

| Button (command)                                       | Step description                           | Display                      |
|--|--|------------------------------|
|  | Turn on machine and standby                | 0.000 g                      |
| Long press [Set]                                       | Press 3 seconds                            | parameter number is blinking |
| Short press [↑] / [↓]                                  | Adjust parameter group number from 1 to 15 |                              |
| If you do not change the data of other parameter items |  |                              |
| Long press [SET]                                       | Return to standby mode                     |                              |

## 4.2 Temperature setting




| Button (command)   | Step description                               | Display                      |
|--|--|------------------------------|
|  | Turn on machine and standby                    | 0.000 g                      |
| Long press [Set]   | Press 3 seconds                                | parameter number is blinking |
| Short press [Set]  | <b>Temperature number blinking</b>             | xxxx°C                       |
| Short press [↑] / [↓]  | Adjust the temperature                         |                              |
| ( Short press [↑] / [↓] will add or decrease the value 1°C , long press will be 5°C) |  |                              |
| If you do not change the data of other parameter items                               |  |                              |
| Long press [SET]   | Three seconds, save and return to standby mode |                              |



## 4.3 Working mode setting

| Button (command)  | Step description                                 | Display                      |
|---|--|------------------------------|
|   | Working mode selection                           | 0.000 g                      |
| Long press [Set]  | Press 3 seconds                                  | parameter number is blinking |
| Short press [Set]   | Temperature number blinking                      | xxxx°C                       |
| Short press [Set]   | <b>The working mode setting is bilinking</b>     |                              |
|   | High precision with automatically working mode   | Auto Hi                      |
|   | Medium precision with automatically working mode | Auto M                       |
|   | Low precision with automatically working mode    | Auto Lo                      |
|   | Timed working mode                               | Time                         |
|   | Manually working model                           | Hand                         |
| Short press [↑] / [↓] to choose the working mode which you need and Short press [Set] to save the setting and exit. |  |                              |
| If you do not change the data of other parameter items  |  |                              |
| Long press [SET]  | Three seconds, save and return to standby mode   |                              |

## 4.4 Heating method setting

| Button (command)  | Step description                              | Display                      |
|-------------------|---|------------------------------|
|                   | Working mode selection                        | 0.000 g                      |
| Long press [Set]  | Press 3 seconds                               | parameter number is blinking |
| Short press [Set] | Temperature number blinking                   | xxxx°C                       |
| Short press [Set] | The working mode setting is bilinking         |                              |
| Short press [Set] | <b>The heating method setting is blinking</b> |                              |

|   |                  |
|---|------------------|
|  | Fast heating     |
|  | Standard heating |
|  | Slow heating     |



Short press [] / [] to choose the heating method which you need and Short press [Set] to save the setting and exit.



If you do not change the data of other parameter items



Long press [SET]                      Three seconds, save and return to standby mode

---

## 4.5 Timed mode – Time setting

| Button (command)  | Step description                           | Display                      |
|---|--|------------------------------|
|   | Working mode selection                     | 0.000 g                      |
| Long press [Set]  | Press 3 seconds                            | parameter number is blinking |
| Short press [Set]   | Temperature number blinking                | xxxx°C                       |
| Short press [Set]   | The working mode setting is blinking       |                              |
| Short press [  ] / [  ) | Circle to timed mode and start to set time | Time                         |
| Short press [Set]   | The flashing position is second            | <b>10:00</b>                 |
| Short press [Set]   | The flashing position is minute            | <b>10:00</b>                 |

**Short press [] / [) to increase or decrease the number of second and minute.**

**Short press [] / [) is increase or decrease 1 and long press is 5.**

**The maximum number of time setting can be 99:00 minutes.**

If you do not change the data of other parameter items

Long press [SET]                      Three seconds, save and return to standby mode

---

## 4.6 Customize mode – The condition of stop measuring

| Button (command)                                       | Step description  | Display                      |
|--|---|------------------------------|
|  | Working mode selection                                      | 0.000 g                      |
| Long press [Set]                                       | Press 3 seconds   | parameter number is blinking |
| Short press [Set]                                      | Temperature number blinking                                 | xxxx°C                       |
| Short press [Set]                                      | The working mode setting is blinking                        |                              |
| Short press [↑] / [↓]                                  | Circle to customize mode and set                            | Hand                         |
| Short press [Set]                                      | Customize mode with heating method setting                  |                              |
| Short press [Set]                                      | Customize mode with condition of stop measuring             | 0.005g                       |
| Short press [↑] / [↓]                                  | to set the minimum changing value which need to be measured |                              |
| Short press [Set]                                      | parameter number is blinking                                |                              |
| Short press [Set]                                      | Temperature number blinking                                 |                              |
| Short press [↑] / [↓]                                  | to set the measure time of drying condition                 |                              |
| If you do not change the data of other parameter items |   |                              |
| Long press [SET]                                       | Three seconds, save and return to standby mode              |                              |

## 5. Moisture analyzer calibration

The moisture analyzer uses the relative weight to measure the result, so a small deviation from the absolute weight has less influence on the accuracy of the measurement. The moisture analyzer is stable in weighing performance and has a small temperature influence, which can maintain the calibration result for a long time, so weight calibration is not necessary. Before calibration, confirm that the Moisture analyzer is empty in the weighing mode, and there is no any other things on the weighing pan.

### Preparation

1. Place the machine on a solid, horizontally position, table or platform and then adjust the level.
2. Turn on and warm up the machine at least 30 minutes.

The calibration/adjustment only can be make in the following situation

The machine will show the calibration weight only if reach below requests

- ※ The machine must be warm up in advance.
- ※ The machine is not overload, already tare the weight, inner signal stable

### 3. External calibration

| Button (command)  | Step description    | Display     |
|---|---------------------|-------------|
| Short press [TARE]  | To tare the machine | 0.000g      |
| Long press [START]  | Press 3 seconds     | CAL 0       |
| The display will flash the calibration weight                     |                     | ⌈ 100.000 ⌋ |
| Put the standard weight mass on pan as display show (example 100g |                     |             |
| After 5 seconds , display will show 100.000g                      |                     |             |
| Remove the weight and the calibration is over.                    |                     |             |


---

## 6. Step of measurement

Note: Please set the heating method and temperature refer to the menu 4.

6.1 Press Tare key, make sure that machine display 0.000g and then put the sample evenly on the weighing tray.

6.2 Close the heating compartment lid, press [START] key to start the measurement when machine display stable.



On the left of display, flash  means machine are under heating condition.

6.3 After finishing, the display will show the sample's moisture value.

Press [Set] can switch to check the other testing result. Press [TARE] key can exit and return to standby mode and wait for a new testing.

Note: 1. During measuring, user can press [STOP] to call off the testing.

2. DO NOT open the lid (cover of heating compartment) during testing.

|   |                             |   |                |
|---|-----------------------------|---|----------------|
|  % | % of water content          |  g | Initial Weight |
| %   | % of solid material content | g   | Current weight |

After finish the test , user can press SET key to check each data of above.

Note: the test results may vary slightly depending on the weight of the sample or the weighing error.

User can optimize the machine and result according to menu 7.

---

## **7. Optimize the testing**

---

During the heat drying process, the moisture is determined by the weight loss of the sample. The speed and quality during the measurement can be referred to the following parameters. The following parameters can also be determined by several trial experiments to determine the best settings. The best test results depend on the following settings:

Heating temperature

Heating time

Sample weight

Sample preparation

Sample species

### **7.1 Heating temperature**

The heating temperature control the measure time long or short. Example, heating temperature low will longer the sample dried time. Set an appropriate heating temperature and make sure that the chemical structure of the sample can neither be decomposed nor changed. It is generally set to 105 °C, except if the sample and user have special requirements.

Some samples have different moisture content at different heating temperatures. In this case, try to adjust the heating temperature to compensate for the measurement deviation.

### **7.2 Heating time**

The moisture analyzer provide three simple way

Auto mode (recommend mode) --- When machine detect a change in weighing results, it automatically stops when the sample weight loss is less than the set value for a specified period of time (usually one minute).

Hand mode --- Moisture analyzer in accordance with the user through menu 4.6 customize mode - stop conditions set weightless values and detection time values, to meet the set condition values when the machine automatically stop.

Timed mode --- The heating time is set manually, i.e. the heating is automatically stopped after the set time, ending the measurement.

Setting range: 0 to 99 minutes.

### 7.3 Sample's weight

★The weight of the sample affects the measurement time and the repeatability of the results, with a maximum sample weight of 50g.

★The more samples on tray , the more water is evaporated and the testing process is prolonged.

★Sample weight is recommended at around 5-10g. Samples of 2g get faster results, but lack of accuracy. Samples of 20g usually get consistent results, but take longer to test.

★Another way to measure sample weight is to use the relationship between sample weight and moisture resolution, as below list:

| Sample weight | Repeatability | Sample weight | Repeatability |
|---------------|---------------|---------------|---------------|
| 0.5g          | ±1.0%         | 5g            | ±0.1%         |
| 1g            | ±0.5%         | 10g           | ±0.05%        |
| 2g            | ±0.2%         | 20g           | ±0.02%        |

For example, if the moisture resolution result need to reach  $\pm 0.3\%$ , in the table, mention that the sample weight should be at least 2g. (The following test data is for informational purposes only)

### 7.4 Sample preparation

Samples need to be representative of the test in order to obtain accurate and repeatable measurements.

When preparing samples, ensure that the samples are placed evenly on the sample tray to avoid build-up and excessive quantities

### 7.5

#### ★Pasty, fat-containing soluble samples

Use fiberglass membranes to increase the surface area of the sample, for example, butter. The water in these substances is distributed more evenly through suction cups. Increasing the surface area of the sample causes water to evaporate faster and more completely

#### ★Liquid samples

Liquids form droplets on the sample tray, which prevents quick drying. In this case, the glass fiber membrane can be used to distribute the liquid sample evenly in a large surface area, which can shorten the drying time.

★Easily crusted, temperature-sensitive samples

Samples that form shells on the surface can completely hinder the measurement of moisture. At this time, use fiberglass membrane covering the sample, and with a milder and more suitable heat, can improve the repeatability of the sample.

★Sugary samples

Samples containing a lot of sugar are easily burn. Make sure that the sample is evenly distributed into a thin layer and set a moderate temperature. Glass fiber suction cups can also be covered in samples to improve their repeatability.

---

## 8. Time Setting

| Button (command)   | Step description                                  | Display |
|--|---|---------|
| Standby status   |   | OFF     |
| Long press [Set]   | Press 3 seconds                                   | T-SET   |
| Later, display will show and flash: year, month, day, hour, minute |   |         |
| Short press [Set]  | move the flash position to set                    |         |
| Short press [↑] / [↓]  | to increase or decrease the setting value         |         |
| Long press [↑] / [↓]   | to quickly increase or decrease the setting value |         |
| Long press [Set]   | Press 3 seconds if all setting finish             | TE-End  |
|  | Save and exit                                     |         |

---

## 9. RS-232 Data communication

### Baud rate setting

| Button (command)   | Step description          | Display |
|--|---------------------------|---------|
| Standby status   |                           | OFF     |
| Long press [TARE]  | Press 3 seconds           | b9600   |
| Display the current baud rate and short press [↑] to circle and set the rate |                           |         |
| Display show: b9600 means the baud rate is 9600                              |                           |         |
| Short press [ON/OFF]   | Save the setting and exit |         |

## 9.1 RS232 Data communication settings (factory default settings)

Baud rate: 9600 (default) (1200、2400、4800、9600、19200 available)


Data bit: 8

Parity: N

Stop bit: 1

Data output way : Press PRINT key to output data

## 9.2 RS232 pin connection



| Machine | Computer | Machine | Serial port printer |
|---------|----------|---------|---------------------|
| 9male   | 9female  | 9male   | 25female            |
| 2       | ----- 2  | 2       | ----- 3             |
| 3       | ----- 3  | 3       | ----- 2             |
| 5       | ----- 5  | 5       | ----- 7             |

## 9 Data communication:

After the test completes a set of moisture values, the moisture value remains until the [Start/Stop] key is pressed. During this period, you can press the [Print] key to output the test value, dry weight of the material, print time, etc. To an external device.

RS232 Output format:

INITIAL WEIGHT:7.909g

FINAL WEIGHT:7.821g

MOISTURE CONTENT:1.11%

DATE TIME:

2015/12/20 11: 03: 30

REMARKS:

Test successfully printed end

## 10. The measurement Data Storage

---

At the end of each test, the test data can be automatically saved by machine, and only the last 20 sets of test data are retained for easy access to view, print, etc.

| Button (command)  | Step description                          | Display |
|---|---|---------|
|   | Standby                                   | 0.000 g |
| Long press [PRINT]  | Press 3 seconds                           | NOTES   |
| The flash save number and data is the last time of moisture measurement |   |         |
| Short press [↓]   | To display the next group of measure data |         |
| Short press [↑]   | To display the last group of measure data |         |
| Long press [PRINT]  | To print the current data                 | PRINT   |
| Long press [ON/OFF]   | Return to weighing status                 |         |

---

## 11. Maintenance and troubleshooting

### 11.1 Meaning of signal

|       |   |
|-------|---|
| O Err | This signal remind user that machine was not covered                                  |
| T Err | Remind user that temperature not increase after start to heat                         |
| Lo    | Remind that the test sample weight is less than the minimum of required sample weight |
| CAL 0 | Remind that machine will calibrate on zero ( no need to put any weight mass on pan)   |
| C 100 | Remind user to put 100g weight mass on pan for calibration                            |
| C EnD | The calibration was successful  |
| C Err | The calibration failed  |

If the fault message cannot be resolved or does not describe the problem with your moisture analyzer, please call our customer service department or your local authorized service agent or company.

### 11.2 Maintenance of machine

Cleaning: For accurate measurement results, it is recommended to clean the temperature sensor and heating silo regularly.

Before cleaning, machine must be unplugged, clean carefully, so as not to damage the instrument, please use a hairless (velvet) soft cloth and neutral detergent cleaning, and never use corrosive detergent. Do not allow the detergent to flow into the inside of the instrument.

Tips: Please turn on and warm up machine for 60 minutes and then calibrate for the first time use.

Every time you turn it on and off, please have an interval of 5 seconds.

If the continuous measurement, please do a new experiment when the temperature is below 40 °C.

When covering the heater, do not leave the weight on the scale, otherwise the halogen lamp will be crushed.

When you leave the moisture meter, be sure to cut off the power supply.

Do not let the moisture meter work without monitoring.

---

## **12. Warranty**

The product has a one-year warranty (from the date of sale). During the warranty period, products with quality problems for replacement or free repair.

Except in one of the following cases:

1. The warranty period has passed.
2. Damage to the moisture meter due to the user's own fault.
3. The user did not operate according to the instructions and caused damage to the moisture meter.
4. Damage to the water meter due to exposure to radioactive or corrosive substances.
5. The user disassembles the machine or repairs caused by maintenance personnel who have not been appointed by our company.



INSTRUMENTOS DE MEDICIÓN INDUSTRIAL



LLÁMANOS

+52(81) 8115-1400 / +52 (81) 8173-4300

LADA Sin Costo:  
01 800 087 43 75

E-mail:  
[ventas@twilight.mx](mailto:ventas@twilight.mx)

[www.twilight.mx](http://www.twilight.mx)



/ [twilightsadecv](#)



/ [twilightsadecv](#)



/ [twilightsadecv](#)