

Torquimetro Ratchet, Drive 3/8

LT-TQ8803

www.twilight.mx







1000 Kgf-cm, heavy duty, professional **TOROUE WRENCH** Model : TQ-8803



Your purchase of this 1000 Kgf-cm Torque Wrench marks a step forward for you into the field of precision measurement. Although this METER is a complex and delicate instrument, its durable structure developed. Please read the following instructions carefully and always keep this manual within easy reach.

OPERATION MANUAL

TABLE OF CONTENTS

1.	FEATURES	1
2.	SPECIFICATIONS	2
	2-1 General Specifications	2
	2-2 Electrical Specifications	3
3.	FRONT PANEL DESCRIPTION	. 4
	3-1 Display	.4
	3-2 Power button	.4
	3-3 LCD backlight button	4
	3-4 Unit button	.4
	3-5 A Button	4
	3-6 ▼ Button	4
	3-7 Handle	. 4
	3-8 Torque force direction switch	.4
	3-9 Battery Compartment/Cover	. 4
	3-10 Screws for battery cover	.4
	3-11 Square drive	4
	3-12 Beeper	4
		_
4.	MEASURING PROCEDURE	. 5
	4-1 Measurement	5
	4-2 Auto data hold	.6
	4-3 LCD backlight ON/OFF	6
	4-4 Alarm setting	.6
	4-5 Auto power off	7
5.	BATTERY REPLACEMENT	. 7

1. FEATURES

- * Professional and Heavy duty torque wrench.
- * Range : 1000 Kgf-cm, 868 lbf-in, 72.3 lbf-ft, 9807 N-cm, 98.1 N-m.
- * Unit : Kgf-cm, Lbf-in, Ibf-ft, N-cm, N-m.
- * Auto data hold function to freeze the last measurement reading.
- * Alarm value setting with beeper sound.
- * Size of square drive : 3/8 inch square (9.52 mm square).
- * LCD display with backlight, easy readout.
- * Auto shut off circuit to save battery life,
- * Microcomputer circuit, high performance.
- * Metallic heavy duty & compact housing case.
- * Power supply : DC 1.5V battery (UM-4, AAA) X 4 PCs.

2. SPECIFICATIONS

2-1 General Specifications

Display	57 mm x 25 mm LCD display.				
Measurement	Torque value,				
function	Auto data hold,				
	Alarm beeper setting.				
Measurement	kgf-cm, lbf-inch, lbf-feet, Newton-cm,				
unit	Newton-meter.				
	* kgf : Kg-force, lbf : pound-force				
Function	5 buttons :				
buttons	Power button				
	Backlight button				
	Unit button				
	▲ button (for alarm setting)				
	▼ button (for alarm setting)				

Sensor	Exclusive torque sensor.		
Circuit	Exclusive microcomputer LSI circuit.		
Data hold	Freeze the last reading automatically.		
Alarm setting	It can set the alarm force value, when		
	measuring value reach the alarm value		
	the beeper will sound, the LCD backlight		
	will flash too.		
Zero adjust	Automatic zero adjustment.		
Size of	3/8 inch square (9.52 mm square).		
square drive			
Power off	Auto shut off, saves battery life,		
	or manual off by push button.		
Power supply	Alkaline or heavy duty type		
	DC 1.5 V battery (UM-4, AAA) x 4 PCs.		
Power	Approx. DC 5 mA (baklight off).		
consumption	Approx. DC 13 mA (baklight on).		
Weight	1050 g (2.3 LB).		
Dimension	450 x 55 x 37 mm		
	(12.2 x 2.0 x1.8 inch).		
Accessories	Instruction manual 1 PC.		
included	Hard carrying case 1 PC.		

2-2 Electrical Specifications (23 5 $^\circ\!\!\!C$)

Display Unit	Max. Range	Min. Range	Resolution				
kgf-cm	1000 kgf-cm	3 kgf-cm	1 kgf-cm				
lbf-in	868 lbf-in	2 lbf-in	1 lbf-in				
lbf-ft	72.3 lbf-ft	0.2 lbf-ft	0.1 lbf-ft				
N-m	98.1 N-m	0.2 N-m	0.1 N-cm				
N-cm	9807 N-cm	20 N-cm	2 N-cm				
* kgf : Kg-force, lbf : pound-force, N = Newton							
* in = inch, ft = feet, m = meter, cm = centimeter							

Display Unit	Accuracy
kgf-cm	
	± 2 % F.S. (full scale)
lbf-in	@ From 20% to 100 % of full scale .
lbf-ft	± (2% reading + 5 d).
	@ 5% to 19 % of full scale.
N-cm	
N-m	

@ Above specification tests under the environment RF Field Strength less than 3 V/M & frequency less than 30 MHz only.

3. FRONT PANEL DESCRIPTION





Fig. 1

- 3-1 Display
- 3-2 Power button
- 3-3 LCD backlight button
- 3-4 Unit button
- 3-5 🛦 Button
- 3-6 ▼ Button
- 3-7 Handle
- 3-8 Torque force direction switch
- 3-9 Battery Compartment/Cover
- 3-10 Screws for battery cover
- 3-11 Square drive
- 3-12 Beeper



4. MEASURING PROCEDURE

4-1 Measurement

- Power on the meter by pressing the "Power Button" (3-2, Fig. 1) once, the Display will show zero value and ready for the measurement.
 - * After power on, if press the "Power Button" (3-2, Fig. 1) once again, the meter will be off.
 - * The minimum measurement value is 50 kgf-cm (43 lbf-in/3.6 lbf-ft/4.9 N-m/490 N-cm), if the measurement value less than 50 kgf-cm, the Display will show " 0 " value.

2) Unit Button

After power on, push the " Unit button " (3-4, Fig. 1) once in sequence to select the measurement unit :

kgf-cm, lbf-in, lbf-ft, N-cm, N-m.

- * After select the desired unit, if power off then power on again, the existing sleet unit will save into the memory circuit with default.
- 3) Set the Torque force direction by slide the "Torque force direction switch " (3-8, Fig. 1).
 - * Set the direction switch to the left, will make the clockwise direction for the torque force measurement.
 - * Set the direction switch to the right, will make the counterclockwise direction for the torque force measurement.

4) Connect the "Square Drive " (3-11, Fig, 1) to the

" Torque adapter " (optional) or the measured

" Measurement Installation " that intend to measure the torque value.

Use the hand to hold the "Handle " (3-7, Fig. 1) firmly and rotate the Handle, the Display will show the measurement torque value.

4-2 Auto data hold

During the measurement, upon Display show the measurement torque value, if release the handle, the last measurement value will freeze on the Display within 10 seconds approximately at the same time the Display will show the "HOLD " indicator.

* During execute the "Auto data hold "function, if make new measurement again, the "Hold function " will be disappeared and return to normal measuring screen.

4-3 LCD backlight ON/OFF

After power on the meter, if press the "LCD backlight button " (3-3, Fig. 1) once will turn on the LCD backlight, if press the "LCD backlight button " once again will turn off the LCD backlight.

4-4 Alarm setting

- After power on , it press the "▲ Button or ▼ Button " (3-5, 3-6, Fig. 1) once or continuously will set the Alarm setting value ".
- 2) *a.* The setting Alarm value will save into the memory circuit with default.
 - b. The "Beeper " (3-12, Fig. 1) will sound slowly if the the measuring value reach the 90% Alarm setting value.
 - c. The "Beeper " (3-12, Fig. 1) will sound quickly if the the measuring value reach the Alarm setting value.

4) The LCD backlight will flash for warning if the measuring value reach the Alarm setting value.

For example :

- * If the Alarm setting value is 500 kgf-cm, the "Beeper" will sound slowly when the measuring value reach to 450 kgf-cm, the "Beeper" will sound quickly when the measuring value reach to 500 kgf-cm.
- * When the measuring value reach to 500 kgf-cm, the LCD backlight will flash for warning too.

4-5 Auto power off

After power on, if do not make any further operation (not change the Display value or not press any buttons), then within 3 minutes the meter will power off automatically to save the battery power energy.

5. BATTERY REPLACEMENT

- 2) Loose the "Screw of the battery cover " (3-10, Fig. 1) and take away the "Battery Cover " (3-9, Fig. 1) from the instrument and remove the battery.
- 3) Replace with DC 1.5 V battery (UM4/AAA, Alkaline/heavy duty) x 4 PCs, and reinstate the cover.
- 4) Make sure the battery cover is secured after changing the battery.

0911-TQ8803



LLÁMANOS +52(81) 8115-1400 / +52 (81) 8173-4300

LADA Sin Costo: 01 800 087 43 75

E-mail: ventas@twilight.mx

www.twilight.mx





