

# **Gaussimetro SP-5170/SP-5180 Rangos 20,000 y 30,000 gauss**

www.twilight.mx







# Actuators Gaussmeters

Motors
Position sensors
Power conversion
Power generation

### Gaussmeters

# 5100 series



The 5100 series Hall effect portable gaussmeters represent the most recent design from the world leader in magnetic measuring equipment. This new design incorporates the use of digital signal processing technology making it the world's first hand-held gaussmeter to have a digital signal processor (DSP) on board. F.W. Bell's exclusive dynamic probe correction allows measurements from 0 to 30 kG with a basic accuracy of 1%.

Key features include auto zero, min./max./peak hold, auto range and relative mode. Both models allow the user to select Gauss, Tesla or Ampere/meter readings. The 5180 features a corrected analog output ( $\pm 3V$  FS) and a USB communication port.

The 5100 series hand-held gaussmeter's built-in software eliminates the need for complex calibration procedures. User prompts on the custom formatted LCD allow fast, simple push button operation. All models come equipped with a detachable transverse probe, zero gauss chamber, instruction manual, hard carrying case, and four AA batteries. Axial, ultra-thin transverse and low-field probes are available as options.

Applications for the 5100 Series range from the most sensitive laboratory environment to the most rugged industrial setting. All instruments are CE compliant.

#### 5180 probes

- HTD18-0604, 4" transverse
- STD18-0404, 4" transverse
- STD18-0402, 2" transverse
- SAD18-1904, 4" axial
- SAD18-1902, 2" axial

#### 5170 probes

- HTH17-0604, 4" transverse
- STH17-0404, 4" transverse
- STH17-0402, 2" transverse
- SAH17-1904, 4" axial
- SAH17-1902, 2" axial

#### 5170/5180 probes

- STB1X-0201, ultra-thin, transverse
- MOS51-3204, low field

#### Accessories

- YA-111, zero gauss chamber
- PSRD-5, AC adapter
- PSRI-5, AC adapter

#### Contact

#### OECO

4607 SE International Way Milwaukie, OR 97222

Tel: +1 (503) 659-5999

www.meggitt.com

www.fwbell.com

www.oeco.com





Power generation

# Gaussmeters 5100 series

## **Specifications**

Model:	<u>5170</u>	<u>5180</u>
Basic DC accuracy	2%	1.1%
Frequency bandwidth	DC- 20 kHz	DC- 25 kHz
Update rate: Display Analog	4 readings / sec. None	4 readings / sec. 100K samples / sec.
Ranges:  Ultra-low range Low range Mid-range High range	1 G 200 G 2 kG 20 kG	1 G 300 G 3 kG 30 kG
Resolution: Ultra-low range Low range Mid-range High range	1 mG 0.1 G 1.0 G 10 G	1 mG 0.1 G 1.0 G 10 G
Display	LCD	LCD
Digits	3.5	3.67
Readings	Gauss, Tesla, Amps/meter	Gauss, Tesla, Amps/meter
Analog output	None	±3 V FS
Communication port	None	USB (1 sample / sec.)
Battery type	4 AA alkaline	
Operating temperature	O°C to 50°C	
Storage temperature	−25°C to 70°C	
Size	6.9" x 3.9" x 1.44"	
Shipping weight- domestic	3.5 lbs. (1.59 kg)	
Shipping weight- international	4.0 lbs. (1.82 kg)	

Note: Due to continuous process improvement, specifications are subject to change without notice





# **ULÁMANOS**

+52(81) 8115-1400 / +52 (81) 8173-4300

LADA Sin Costo: 01 800 087 43 75

E-mail: ventas@twilight.mx



